



Currently, we are working on cleaning the tipping buckets and reinstalling them. We took them apart and scrubbed them with brushes. After scrubbing, we rinsed them with bleach and water making sure that they are fully drained